

Ambient Bamboo Floors

8125 Stayton Dr Unit C Jessup, MD 20794 USA

ASTM D 6007

Report Date:	
Project #:	
Report Of:	ASTM D 6007
	0721473-21
	2016-0983
Reporting Lab:	Benchmark Holdings, LLC 2710 West 5th Avenue, Eugene, OR 97402 USA Phone:541/484-9212 - Fax: 541/344-2735

ASTM D6007	Determining	
Chamber Results		
	Impinger	
	#1	
Observed Flow Rate (I/m):	1.000	
Corr. Vol. of Air Sample:	29.623	
Raw Absorbance Values:	0.003	
	0.004	
	0.010	
Average Absorbance:	0.006	
Unadjusted PPM:	0.016	
Temp. Correction Factor 77°F:	0.94	
R.H. Correction Factor 50% RH:	0.95	
Standardized Concentration PPM:	0.014	

Production Data					
Product: Strand Bamboo HDF Click-Lock Flooring 10mm					
Mill Code:	NS	Prod Date:	NS		
Prod Group:		Control Date:	NS		
Test Date:	7-Apr-16	Coll. Date:	22-Mar-16		

CHAMBER ID#:				
Chamber Conditions				
Barometric Pressure (in):	29.60			
Dry Bulb Temp (°F):	78.00			
Relative Humidity (%):	52.40			
Length of Test (minutes):	30.00			

Comments: *Sample is engineered bamboo flooring, tested as if it were HWPW.

<u>Parameters:</u>						
Loading Ratio:	0.430	Volume =	.1191863m³			
Chamber Dimensions:	.49213m x .49213m x .49213m					
Air Exchange Rate:	0.50 ± 0.05 air changes per hour					

^{*}The chamber is activated under positive pressure. The air sampling rate was 1.0 liters per minute at 30 ±2 minutes.

*This report has been produced for the exclusive use of:

Ambient Bamboo Floors

(client),

and may not be reproduced except in its entirety, and only with the expressed, written approval of BMI. No one other than BMI's client shall be entitled to rely upon this report or the information contained herein. Any such unauthorized reliance on or use of this report will be at the third party's sole risk.

ACCREDITED

Respectfully Submitted,

Benchmark Holdings LLC

Travis R. Snapp

Managing Director / COO
Benchmark International LLC

^{*}The samples were conditioned for seven days prior to testing at 70° to 80° F and 45% to 55% relative humidity. During conditioning, the formaldehyde background level was 0.01 parts per million or less.

^{*}Services performed for this project have been conducted with a level of care and skill ordinarily exercised by members of the profession currently practicing in this area under similar conditions and restraints. No warranty, expressed or implied, is made.